


evolution System Camera Connection Overview



RS Cables

| | | | |
|-------|-------------------------------|------------|----------|
| RRS-5 | Supply Cable | Open Ended | C019-K35 |
| RRS-6 | Battery Supply Cable | XLR m4p | C019-K36 |
| RRS-7 | Anton Bauer Supply Cable | AB m2p | C019-K37 |
| RRS-9 | Sachtler Artemis Supply Cable | Le, m2+f2p | C019-K39 |
| RRS-A | RS Supply Cable | Fi m11p | C019-K3A |
| RRS-B | PSTechnik Pro35 Run Cable | Fi m3p | C019-K3B |
| RRS-C | PSTechnik Mini35 Run Cable | Fi m3p | C019-K3C |
| RRS-E | Steadicam Ultra2 Supply Cable | Le m3p | C019-K3E |
| RRS-F | Chrosziel Supply Cable | Hi m3p | C019-K3F |
| RRS-G | MKV Supply Cable | Le m3p | C019-K3G |
| RRS-H | Battery Supply Cable | XLR f3p | C019-K3H |